

S/015/051

DOGAL REC.
7/31/96



A. Culvert adjacent ot the access road in T.21S., R.7E., Section 34, Ron Wright, notice UTU-68020. 7-23-96..



B. Bulldozer parked adjacent to the access road across from the culvert in T.21S., R.7E., Section 34, Ron Wright, notice UTU-68020. 7-23-96..

9/015/051

DOB REE.
7/31/96



C. Area adjacent to the access road from which junk has been removed in T.21S., R.7E., Section 34, notice UTU-68020, Ron Wright. 7-23-96.



D. Portal to the mine in T.21S., R.7E., Section 34, Ron Wright, notice UTU-68020. 7-23-96.

3/015/091
DEGM REC
7/31/98



E. Area just north of the portal from which junk has been removed in T.21S., R.7E., Section 34, Ron Wright, notice UTU-68020. 7-23-96.



F. Materials stacked neatly against the cliff face and north of the portal in T.21S., R.7E., Section 34, Ron Wright, notice UTU-68020. 7-23-96.

5/09/05/

DOBH REC.
7/31/96



HUH?

G. Petroleum products staomong tje grpimd wjere tje bi;;dpzer used to be parked adjacent to the portal in T.21S., R.7E., Section 34, Ron Wright, notice UTU-68020; 7-23-96.



H. Area of operations north of the portal In T.21S., R.7E., Section 34, Ron Wright, notice UTU-68020. 7-23-96.

S/O15/051
DOBH REC.
7/31/96




- I. Erosion on the access road where it crosses the wash just south of the county road in T21S., R.7E., Section 34, Ron Wright, notice UTU-68020. 7-23-96.

5/015/051



A. Culvert along access road, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 5-30-96.




B. Junk beside the access road, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34.




5/019/051

A. Erosion around the culvert in the wash near the county road, Ron Wright, Notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.



B. Closeup of the erosion on the access road, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.

5/05/05/




C. Abandoned culvert along the access road to the Reefer mine, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.



D. Junk along the side of the access road, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.

5/013/051



- E. Erosion occurring near the second culvert installed in the canyon, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.



- F. Reefer mine portal, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.


5/015/051



G. Rockfall on the north side of the portal, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.



H. Fallen timber support in the Reefer mine, Ron Wright, notice UTU-68020, in T.21S., R.7E., Section 34. 4-16-96.




3/015/051



I. Rusting bulldozer located to the northwest and just outside the portal, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.



J. Rear end of the bulldozer with the portal in the background, Ron Wright, notice UTU-68020, in T.21S., R.7E., Section 34. 4-16-96.




5/015/051



K. Corroding battery inside the bulldozer, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.



L. Lumber and miscellaneous equipment adjacent to the bulldozer, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.



5/015/051



M. Broken battery located just north of the bulldozer, Ron Wright, notice 68020 in T.21S., R.7E., Section 34. 4-16196.



N. Looking to the west down the access road from the cliff top, Ron Wright, notice UTU-68020 in T.21S., R.7E., Section 34. 4-16-96.

